

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave. St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:** Pursell, Gary**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-002636**Date Inspected:** 05-May-2007**Project Name:** SAS Superstructure**OSM Arrival Time:** 1400**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 2330**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China**CWI Name:** Chen Xi**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** OBG/Tower**Summary of Items Observed:**

The Caltrans Quality Assurance (QA) Inspector Roscoe Dixon was present at the time requested to randomly observe welding and associated operations being performed for the Orthotropic Box Girders (OBG).

Bay 3 – New Tower Building

The QA Inspector observed ZPMC qualified welder Xu Guoyin ID 05944 utilizing WPS-345-FCAW-2G (2F) Repair to perform Flux Core Arc Welding (FCAW) repairs of deck panel Partial Joint Penetration (PJP) welds on DP057-001.

The deck panel repair welding in the progress on DP057-001 generally appeared to conform to contract specifications.

The QA Inspector, at the beginning of the shift inventoried and located the following 16 deck panels in New Tower Building Bay #3 on this date: DP054-001, DP002-001, DP008-001, DP015-001, DP014-001, DP002-002, DP055-001, DP049-001, DP057-001, DP018-002, DP004-001, DP063-001, DP001-001, and DP020-001, DP051-001, and DP056-001. The noted during the shift that two deck panels

WELDING INSPECTION REPORT

(Continued Page 2 of 2)



Summary of Conversations:

As noted within the report shown above.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Mazen Wahbeh, (818) 292-0659, who represents the Office of Structural Materials for your project.

Inspected By:	Dixon,Roscoe	Quality Assurance Inspector
Reviewed By:	Carreon,Albert	QA Reviewer
